

Oil Field Environmental Incident Summary

Incident: 20151124102036 **Date/Time of Notice:** 11/24/2015 10:20

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: CHEEK 1

Field Name: TEMPLE

Well File #: 7556

Date Incident: 11/23/2015 **Time Incident:** 14:00

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 8

Qtr: SW SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1500 Feet

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	14	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Oil misting approximately 300 feet off site to the southeast.

Potential Environmental Impacts:

None. No water sources in vicinity.

Action Taken or Planned:

The well was shut in and vacuum truck was called to recover pooled fluid. Area to be mowed. Impacted soil to be scrapped and taken to disposal. Repairs to treater will be completed after cleanup of impacted area off site.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 11/24/2015 **Status:** Correspondence

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the company contact, the treater spilled 14 bbls of oil onto the well site within the dike. The amount missing was approximately 25 bbls, so 11 bbls traveled off of the well site. Directly adjacent to the dike, the soils were saturated. Beyond this area of saturation, a spray covered some vegetation in the field but did not seem to be present on the underlying soil. Murex is planning to excavate the saturated soils and the dike within the well site. Murex is also planning to cut down and dispose of the affected vegetation from the field. Murex is in contact with the landowner. The company contact plans to take soil samples. I requested the company provide to the NDDoH test results and photos of the impact.

Date: 11/24/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to report, the release impacted areas off location. Further followup required.

Date: 12/1/2015 **Status:** Correspondence

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The company representative supplied photos of the spill. These photos can be found in the corresponding folder.

Date: 10/5/2016 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 10:30 a.m. Wind out of the west at 40 mph. Weather was overcast and snowing with a temperature of 31 degrees F. The field surrounding the oil pad was planted and harvested soybeans. The area of impact located east of the pad showed good growth of soybeans in the two rows left alongside the pad. There was no visible staining of the soil off pad, and the water off pad had no visible sheen. No additional follow-up needed for site.